

---

**REPORT**

**SANITARY SEWER  
INSPECTION**

**LOCATION: DRISCOLL  
SCHOOL WILTON, CT**

---

**FOR**

**MR. TY TREGELLAS**

**TURNER CONSTRUCTION CO  
440 WHEELERS FARM RD, STE 301  
MILFORD, CT 06460**

**Office: 203-214-6810  
E-Mail: [stregellas@ttco.com](mailto:stregellas@ttco.com)**

**Report submitted by:**

**ACS**

**(Admiral Conservation Services II, Inc.)  
PO Box 448 Georgetown, CT 06829 203.544.7190  
[www.acsunderground.com](http://www.acsunderground.com)**

---

**September 2012**

## **BACKGROUND**

Admiral Conservation Services (ACS) was commissioned by Turner Construction Company for The Town of Wilton to perform a sanitary sewer line inspection at the Miller Driscoll School located on 217 Wolfpit Road in Wilton, Connecticut.

The specific sewer lines ACS inspected were determined by the on site supervisor, Tim Corcoran, at the school, due to his extensive background knowledge of these sanitary lines. This is the report outlining the approach and recommendation.

## **APPROACH**

A manual push camera was used to inspect the sanitary sewer lines with access gained through a manhole. Once access was gained into the 2" line, a manual push camera was inserted and pushed through the line and recorded the interior condition of the pipe. The images were simultaneously viewed on a monitor and recorded.

Our technician began the pipe inspection at manhole "D" at the rear of the school following the length of the 170' pipe and found it in good condition on August 22, 2012.  
(See image 1)

ACS went on to inspect another section of the pipe at the Miller section of the school. Four manhole covers were lifted and observed with site supervisor. (See image 2 [a,b,c,d]) Out of the four manholes (a, b) were filled with water (c) the clean out would not open (d) was at full flow. Site supervisor advised technician that this was normal flow and there was no need to video inspect this section as blockages or backups had never occurred on this line before.

All recorded video footage in DVD format have been provided to the Client.

## **RECOMMENDATION**

The video inspection concluded the line was clear with no visible line damage and/or obstructions. ACS recommends performing additional video inspection in 6 months to further observe any changes in sewer line.

---

Miller Driscoll School  
217 Wolfpit Road  
Wilton, CT

August 22, 2012

